

PROACTIVE PRODUCTION READINESS



Contents

- Context
 - The opportunity
- Phases of Lean Process Creation
- Check & Adjust
- Logic for you customization
 - Your unique journey
- Some tools
- Thoughts on getting started
- Q&A

The opportunity


• \$400 MM



• Where's the PDCA?



Generic Phases of Lean Process Creation




KIKIKIK 90 days after SOP

Process install

System grooming / Run-off

Process Experimentation and learning


Logic for Your Customization "Embrace your unique current state"



WORKSHEET: 10 minutes

WHO ARE YOUR STAKEHOLDERS?	WHAT DO THEY WANT / NEED?	HOW MIGHT YOU MEASURE THAT 90 DAYS AFTER Start Of Production (SOP)?
1 CUSTOMER	PERFECT QUALITY	Parts Per Million(PPM) DEFECTIVE
2		
3		
4		
5		
6		

DISCUSSION



WORKSHEET – 5 minutes Let's look at ONE Start Of Production Measure

What's the SOP measure?

What could it be during ramp-up?

- What could it be during run-off?
- What could it be during process build?

DISCUSSION – 5 minutes Let's look at ONE Start Of Production Measure

- What's the SOP measure?
 - On-time delivery
- What could it be during ramp-up?
 - Percent finished goods buffer fill
- What could it be during run-off?
 - Percent cycle time attainment
 - Percent kanbans in place
- What could it be during process build?
 - Percent cycle time attainment

Tools

Check list

Score Card

Glide paths

Can be a combination of the items above

Checklist

CRITERIA	COMPLETE? (Y OR N)

% COMPLETE


SOP	<100%	100%
Prior to Ramp-up	<85%	≥85%
Prior to Grooming & RO	<50%	≥50%
Prior to Process Build	<20%	≥20%

Score Card


			% of category	OBSERVED	
CATEGORY	% of Score	SUBCATEGORY	score	MEASUREMENT	
QUALITY	35%	Incoming parts PPM Errorproofing readiness	25% 25%		
		DDM defective vs. projected in A.D.	250/	100%	
		TRIAL DESC		GREEN	RED*
	E	arly trial		50% - 100%	< 50%
		ractice run at rate		70% - 100%	< 70%
DELIVERY				80% - 100%	< 80%
2000				90% - 100% AND	
				a total of 25% in	
				the categories of	
PRODUCTIVITY	20%			SAFETY and	
	S	OP run at rate		SYSTEM	< 90%
			category score.	34/0	
SAFETY	15%	Safety & ergonomics approval	100%	100%	
			Category score:	100%]
SYSTEM READINESS	10%	All gages available & approved	20%	100%	
		All tools available & approved	20%	100%]
		Drawings available at correct releases	20%	100%	_
		Dimensional compliance of parts	10%		
		Functional performance of parts	10%		
		All documents in place	20%		-
			Category score:	80%]

TOTAL SCORE: 96%

Glide Path



Another Glide Path



Thoughts on getting started

- "Better than now"
 - Pick a point & get started
 - Engage stakeholders in the development and improvement of the measures
 - The measures will be "wrong" to start
 - Plan the data collection in each phase
 - Forms
 - Roles & responsibilities

Data collection plan example

Score Card: Data Collection Layout

PPM target (in percent): Productivity target (pph): START TIME: END TIME: OE target: Number of finished goods produced: __ Number of finished goods scrapped + reworked: Any containment findings? STN3 STN6 This data for every station STN2 STN7 STN1 STN8 List of finished goods PNs List of tooling for area (all available?) List of gauges for area (all available?) Pack Are all Q59000 documents in place? O = Okay Out X = Not okay

KEY POINTS:

- KNOW all of the input date required to do your calculations
- Make it clear who is collecting what and when

Questions?

